


ROSE CREEK WATERSHED OPPORTUNITIES ASSESSMENT


Trail and Recreational Issues



Erosion
Storm drain run-offs have created deep and wide gullies from the residential land uses on the mesa to the bottom of the canyon and could potentially affect trails




Lack of amenities
Lack of parking and restrooms for users accessing Rose Canyon Open Space from Genesee Ave and Regents Road.



Erosion
Highly eroded tributaries have begun to erode adjacent trails




Closed railroad crossing
Lack of appropriate railroad crossings force users to unsafely cross the railroad tracks



Disconnected trail system
Non-existing trail connection between Marian Bear Memorial Park and Rose Canyon Open Space



Unsafe creek crossing
Users must cross Rose Creek without a bridge or safe path to access the Marian Bear Memorial Park trail system.



Creek crossing
Numerous stream intersections without means to cross them safely



Disconnected trail system
Users must cross Genesee Avenue to connect the trail system of Marian Bear Memorial Park

LEGEND

- Highways
- Major Roads
- Hydrologic Features
- Existing Trail System
- Rose Creek Watershed Boundary
- MCAS Miramar
- City of San Diego Parks
- Community Plan Areas

0 800 1,600 2,400
Scale in Feet

